

# Workman DM-5000

## Programming Instructions



1. Release the red button on the mic (out)
2. Plug the programming cable into the mic and the computer. (plug with the red wire goes into the mic.)
3. Turn down the volume on your MP3 player all the way till just one notch of audio, do the same for main volume. You will have all the volume levels down low as they can get (not off). Record it to the computer file in lower volume too, real low.
4. Press the red mic button in.
5. Press play on the MP3 Player at the same time you press the red button on the program wire.
6. Let go of that red button when the recording is finished.
7. release the red button on the microphone so that it is OUT.
8. remove the cable jumper.
9. Press the mic red button back IN and leave it there.

To give you an idea how low the volume must be...there can be no discernible sound from your speakers and the recording will still be too loud and distorted.

These instructions prepared by:

*BELLS CB*  
*A Div of CAT Enterprises*  
*5051 NE 12th Ave*  
*OAKLAND PARK, FL. 33334*  
*1-888-561-8131 (orders)*  
*1-954-771-8161 (all other business and tech support)*  
*<http://www.bellsb.com>*